


# Machine mounts fail safe


type Triflex

Art.Code	L (mm)	Ls (mm)	K (mm)	H (mm)	B (mm)	BS (mm)	M (mm)	d1 (mm)	d2 (mm)	Sh A
PC100045	120	100	60	40	60	-	M12i	11	14	45°
PC100055	120	100	60	40	60	-	M12i	11	14	55°
PC100065	120	100	60	40	60	-	M12i	11	14	65°
PC100075	120	100	60	40	60	-	M12i	11	14	75°
4.M12x100VERZ	Height adjustable spindle M12 x 100 complete									

- L = length
- Ls = spacing mounting holes
- K = diameter lid
- D = diameter
- H = height
- B = width
- M = screw thread
- d1 = bore diameter width
- d2 = bore diameter length
- d3 = bore diameter length
- Shore A = hardness



## Load Fz



Ratio horizontal stiffness  
Cx (longitudinal) and Cy  
(transverse direction) compared  
to Cz (load direction)  
Cz : Cx : Cy  
1 : 2,5 : 0,75




# Machine mounts fail safe


type Triflex

Art.Code	L (mm)	Ls (mm)	K (mm)	H (mm)	B (mm)	BS (mm)	M (mm)	d1 (mm)	d2 (mm)	d3 (mm)	Sh A
PC140045	184	140	75	50	75	-	M16i	13	20	30	45°
PC140055	184	140	75	50	75	-	M16i	13	20	30	55°
PC140065	184	140	75	50	75	-	M16i	13	20	30	65°
PC140075	184	140	75	50	75	-	M16i	13	20	30	75°
4M16x110VERZ	Height adjustable spindle M16 x 110 complete										

- L = length
- Ls = spacing mounting holes
- K = diameter lid
- D = diameter
- H = height
- B = width
- M = screw thread
- d1 = bore diameter width
- d2 = bore diameter length
- d3 = bore diameter length
- Shore A = hardness



Load Fz



Ratio horizontal stiffness  
Cx (longitudinal) and Cy  
(transverse direction) compared  
to Cz (load direction)  
Cz : Cx : Cy  
1 : 2,7 : 0,7




# Machine mounts fail safe


type Triflex

Art.Code	L (mm)	Ls (mm)	K (mm)	H (mm)	B (mm)	BS (mm)	M (mm)	d1 (mm)	d2 (mm)	d3 (mm)	Sh A
PC182045	230	182	112	70	112	-	M20i	18	26	34	45°
PC182055	230	182	112	70	112	-	M20i	18	26	34	55°
PC182065	230	182	112	70	112	-	M20i	18	26	34	65°
PC182075	230	182	112	70	112	-	M20i	18	26	34	75°
4M20x150VERZ	Height adjustable spindle M20 x 150 complete										

- L* = length
- Ls* = spacing mounting holes
- K* = diameter lid
- D* = diameter
- H* = height
- B* = width
- M* = screw thread
- d1* = bore diameter width
- d2* = bore diameter length
- d3* = bore diameter length
- Shore A = hardness



Load Fz



Ratio horizontal stiffness  
Cx (longitudinal) and Cy  
(transverse direction) compared  
to Cz (load direction)  
Cz : Cx : Cy  
1 : 2,6 : 0,85




# Machine mounts fail safe


type Triflex

Art.Code	L (mm)	Ls (mm)	K (mm)	H (mm)	B (mm)	BS (mm)	M (mm)	d (mm)	Sh A
PC270045	330	270	221	111	190	135	M24i	22	45°
PC270055	330	270	221	111	190	135	M24i	22	55°
PC270065	330	270 </td <td>221</td> <td>111</td> <td>190</td> <td>135</td> <td>M24i</td> <td>22</td> <td>65°</td>	221	111	190	135	M24i	22	65°

- L* = length
- Ls* = spacing mounting holes
- K* = diameter lid
- D* = diameter
- H* = height
- B* = width
- M* = screw thread
- d1* = bore diameter width
- d2* = bore diameter length
- d3* = bore diameter length
- Shore A = hardness



Load Fz



Ratio horizontal stiffness  
 Cx (longitudinal) and Cy  
 (transverse direction) compared  
 to Cz (load direction)  
 Cz : Cx : Cy  
 1 : 2,3 : 0,6

